

## VILLAGE INFANTS BUILDING REPORT TO GOVERNORS

PERIOD COVERED: AUTUMN TERM 2024/25

### **Sports Hall Flooring**

During a particularly rainy period in the Autumn Term, the flooring in the sports hall became raised. This resulted in the sports hall being out of use for a couple of weeks. The Local Authority funded an investigation to determine the cause of the raised floor. Additionally, the underfloor heating was not working properly. Once the heating issue was resolved, the flooring began to dry out. It's suspected that the raised flooring was caused by a downpipe being installed just below the damp course. We've been informed that more rain is needed to confirm this, and if that's the case, the Local Authority will address the issue.

### **Burst Water Main**

On the lead up to Christmas a burst water main in Ford Road impacted the school, as well as the Ford Road Children's Centre and William Ford School. Fortunately, the waterboard collaborated with the school to allow access to toilets and handwashing facilities, ensuring that all three sites remained open.

### **Nursery Alley Entrance – Uneven Paving**

The path leading to the nursery entrance was very uneven, posing a tripping hazard for anyone using it. The Local Authority funded the resurfacing of the area with new tarmac.

### **School Roof – Leaks**

Repairs to the school roof, which are being funded by the Local Authority, are still pending. At the moment, leaks are affecting the nursery, school kitchen, ICT suite, and the shared area in Year 2. We will provide the Governing Board with an update as soon as we receive more information.